## Work Order ID 51250

Н



Page 1

August 12, 2009 4:13:37 PM

Item ID:

D2221-1

Accept

Setup Start

Stop



**Revision ID:** Item Name:

Rib

**Start Date:** 08/12/2009 **Required Date: 08/18/2009** 

**Start Qty: 12.00** 

Req'd Qty: 12.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan: \_\_\_\_\_\_ Date: O9-18-12 Tooling:

Date:

Start Run



Date: \_\_\_\_\_ SPC (Y/N):

Date:

Stop

Reject Insp.

Sequence ID/ Work Center ID

Operation **Description** 

**Revision Nbr** 

Set Up/ **Run Hours** 

Draw Number Draw Plan Rev. Code

Accept Qty

Reject **Qty** 

Number Stamp

**Draw Nbr** 

D2221

Rev H

0.00

100 Large Fab

Large Fab

Memo

0.00

Large Fab

1- Cut as per dwg D2221 \( \precedut{2}\)2- Deburr and remove identification markings on tube

SAD 09-08-17 (12)

110

QC5- Inspect part completeness to step on W/O

Identify as per dwg & Stock Location:



Quality Control

Memo

120

Packaging

0.00

SAD 09-08-17 (12)

Memo

0.00

Packaging

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O-	•		14/6	DI ODDED OUANG	\			,	
W/O:	T		wc	RK ORDER CHANG	iES				·
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<u>.</u>						<u> </u>			
		•							
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date:	
		esolution:							
NCR:			WORK ORDI	R NON-CONFORM	ANCE (NC	R)			
DATE		Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng			ion C	Chief Eng	QC Inspector
									ļ.

## Work Order ID 51250



Page 2

August 12, 2009 4:13:37 PM

Item ID:

D2221-1

Η

Item Name: Rib

**Start Date:** 

**Revision ID:** 

08/12/2009

**Start Qty: 12.00 Required Date: 08/18/2009** 

Req'd Oty: 12.00

Accept



Run

Setup Start



Stop

Start

Stop

**Cust Item ID:** 

**Customer:** 

Reference: **Approvals:** 

Process Plan:

Operation

Description

Tooling: Date: Date: \_\_\_\_\_\_

Set Up/

**Run Hours** 

SPC (Y/N):

Draw

Number

Rev.

Date:

Date:

Draw

Plan

Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

130

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Quality Control

Dart A	Aeros	pace	Ltd
--------	-------	------	-----

		<del></del>								
W/O:		WORK ORDER CH						74.7	. ,	
DATE	STEP	PF	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Ca	tegory:	NC	R: Yes	No <b>DQ</b>	A:	Date: _	
	. R	esolution:	Disposit	ion:	Q <i>A</i>	: N/C CI	osed:		Date:	
NCR:			WORK OR	DER NON-CONF	ORMANC	E (NCF	R)			
DATE	STEP	Description of NC	Description of NC Corrective Action			7-01-0	Verific	cation	Approvai	Approval
	0.2.	Section A	Initial Chief Eng	Action Descri	ption	Sign & Date		on C	Chief Eng	QC Inspector
						·				
					٠					
									-	
				·						
								J.		

## **Picklist Print**

August 12, 2009 4:13:37 PM

Work Order ID: 51250

Parent Item: D2221-1RevH

Parent Item Name: Rib

arent Item (value)

Comments:



Start Date: 08/12/2009

**Required Date:** 08/18/2009

**Start Qty: 12.00** 

Required Qty: 12.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
M304TS0.750W.065		Purchased	No			100	f	1,622.886	101.0526			


304 SQ Tube .75x.75x.065W

Warehouse	Loc Qty	Loc Code	
<b>Location</b>		•	
Main Warehouse			
MAT	6.307103691		
112051	-0.7368363		
112263	7.04394		
Main Warehouse			
WA	1616.5789		
112263	16.5789		
112344	600		101.0526
112398	1000		

Page 1

Dart Aerospace Lte	<b>a</b>
--------------------	----------

W/O:		·	V	VORK ORDER CHANGI	ES					
DATE	STEP	PROC	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,								
										1
Part No	:	PAR #:	Fault Ca	tegory:	_ NCI	R: Yes	No <b>DQ</b>	<b>A</b> :	_ Date: _	
	R	esolution:	_ Disposit	ion:	_ QA	: N/C Cld	sed:	<del>,</del>	Date:	
NCR:	,	Wo	ORK OR	DER NON-CONFORMA	NCE	(NCR	) .			
DATE	STEP	Description of NC		Corrective Action Section	on B		Verification		Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
	-			•		•				-
					•		,	,		
		,								
							-			
				· ·					•	
									· · · · · · · · · · · · · · · · · · ·	
·										
										į.



Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:			, WC	ORK ORDER CHAN	GES							
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							÷					
····												
•									i			
Part No	:	PAR #:	Fault Cate	gory:	NCF	R: Yes 1	No DQ/	<b>A</b> :	Date:			
				Disposition: QA								
NCR:		:	WORK ORD	ER NON-CONFORM	IANCE	(NCR)	)			-		
DATE OTED		Description of NC	Description of NC Corrective			VAI				√Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Approval Chief Eng	QC Inspector		
		•										
				·								
								<del>.</del>				
					,							
<del></del>				-			<u> </u>					
								,				
	1 1		1		1					1		